

Project No. 823-66078  
Laboratory No. SPT-60104  
Report Date: December 20, 1996

REPORT OF: Accelerated Weathering of Rough Sealmark Coating

REPORT TO: Sealmark Corporation

---


### PROCEDURE

Five (5) specimens were coated on the front and sides of the test plates with Sealmark coating. The specimens were then placed in a weathometer and exposed for a 2000 hour duration.


### RESULTS

No visible signs of cracking, checking, crazing, erosion other characteristic that would effect the performance of the coating were detected.

Prepared by:

  
Paul Medwig  
Laboratory Supervisor

Reviewed and approved by:

  
Tim Barefoot, Manager  
Special Test Department

*Information To Build On*