

消防處  
防火總區

香港九龍尖沙咀東部廣莊道1號5樓  
消防總部大廈



FIRE SERVICES DEPARTMENT  
FIRE PROTECTION COMMAND

FIRE SERVICES HEADQUARTERS BUILDING,  
No. 1 Hong Chong Road, 5/F.,  
Tsim Sha Tsui East, Kowloon,  
Hong Kong

本處檔號 Our Ref.: (32) in FP 207/0005 VIII

來函檔號 Your Ref.:

電訊掛號 Telex: 39607 HKFSD HX

圖文傳真 Fax: 852-2723 2197

} (24 小時 Hours)

電話 Tel. No.:

2733 7744

20 November, 1998

Idealand Buildings Supplies Ltd.  
1/F., Po Shing Industrial Building,  
23 Tai Yau Street,  
San Po Kong,  
Kowloon

Dear Sirs,

**Approval of Products**

I refer to my interim reply on 3.9.1998 on the captioned subject.

The proposed use of the following fire retardant product, which was certificated by the Warrington Fire Research Consultancy (WFRC), is acceptable to this Department :-

|                          |   |  |
|--------------------------|---|--|
| <b>Manufacturer</b>      | : | Sealmark   |
| <b>Model</b>             | : | Sealmark Fire Retardant Coating  |
| <b>Substrate</b>         | : | "Durock Exterior Cement Board", a PVC coated glass fibre mesh faced cement board |
| <b>Standard Achieved</b> | : | Class 1 of BS 476 : Part 7 : 1997  |
| <b>Test Report</b>       | : | WARRES No. 102641 dated 11.5.1998 issued by WFRC                                 |

...../P.2

Please note that the acceptance of the above is subject to :-

- (i) all conditions as stipulated in the above-mentioned test report being complied with; and
- (ii) the application of the captioned products shall be carried out by a registered Class 2 Fire Service Installation Contractor.

Yours faithfully,



(LAU Shu-lam)  
for Director of Fire Services

LSL/LKB/lcw